


CERTIFICATION by CUSTODIAN of RECORDS Tucson Police Department Crime Laboratory





I hereby certify that these documents are a true and correct copy of the periodic maintenance* for the Intoxilyzer 5000 Serial Number 64-001226 (#8) maintained by the Tucson Police Department Crime Laboratory pursuant to the requirements of the Arizona Department of Public Safety for a quality assurance program.

A quality assurance specialist (QAS) tested the instrument on the following dates. The acceptable accuracy limits, as defined in A.A.C. R9-14-404.A.3, for a 0.080AC solution are 0.070AC to 0.090AC.

Date: 4.17.2006	Cal 1 0.077	_AC	Cal 2 0.080	AC
Date:	Cal 1	_AC	Cal 2	_AC
Date:	Cal 1	_AC	Cal 2	_AC
Between the dates of _ the instrument was ope	erating properly and a	accura	nd tely.	
The instrument was ta	turned to service on _	al	t·17·06	·
	4.19. 2000 ADPS QAS Permit	# OAS	5 976	C
SUBSCRIBED AN	ND SWORN to befor		his <u>/9</u> , day o 0 <u>06</u> .	İ
OFFICIAL SEAL KATHY A. KINNEY NOTARY PUBLIC-ARIZONA	Kath City			
PIMA COUNTY My Comm. Exp. Sept. 4, 2008	V			

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

^{*}Includes documents specified in A.A.C. R9-14-404.A.6



MEMORANDUM

DATE:

March 29, 2006

TO: Applied

Applied Electronics 52 Juniper Lane P.O. Box 658 Eagle, CO 81631 FROM:

Jennifer L. Coombs

Tucson Police Department

Crime Laboratory 270 S. Stone Avenue Tucson, AZ 85701-1917



SUBJECT: Intoxilyzer 5000 Maintenance and Repair

Enclosed is Intoxilyzer 64-001226 (#8).


Reason: During the initial diagnostic checks the instruments displays "Processor Error 1".

Please repair.

OMER SERVICE REPORT		DEPT,		STATE	P.O. NO.	PHONE ()	FNT RECEIVED INVENTORY	ING CASE EXTENSION C	CABLE TUNING FORK POUCH PAT BOX	LOCK TUNING FORK POUCH SIMULATOR	DASH BRACKET BATTERY PACK BREATH TUBE	DECK BRACKET	BRACKET [A/C POWER CORD No. (1)	DESCRIPTION OF CHARGES FART NO. OTY UNIT PRICE TOTAL	\dashv	H0071 3	Chopper Weter 3400251	(careator			Courses (Ed.		and the state of t	LA POINTER	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
CUST	RECEIVED FROM	DEPT.	STREET 270 S Steine Mas	STATE LASSIN		PHONE ()	H ₩ d 1 1 0 H		30/22(, ECM		ANTENNA SER.NO.	E.C.M./VM SER.NO.	TUNING FORK SER.NO.	TUNING FORK SER, NO.	MISC.SER.NO.		CUSIQMER COMPLAINT / SERVICE REQUESTED	Locassor enail	ł		Lon Jaken	Traces of the second se	The state of the s	or Cleaned Overes	

FACTORY AUTHORIZED WARRANTY SERVICE FACILITY FOR ALL CMI AND MPH PRODUCTS





Statutes, this document is a certified duplicate of the information contained in computer storage Factory Authorized Service Facility For CMI/MPH Produir devices of the Tucson Police Department.



• P.O. BOX 658 • EAGLE, CO 81631 Phone: (970) 328-5420

STATEMENT OF SERVICE WARRANTY

Applied Electronics warrants that any component having been replaced, to be free of defects in material and workmanship for a period of 90 days from date of delivery to its customer. This warranty is limited to only components that have been replaced during the repair of your product. Applied Electronics obligation is limited to repairing or replacing as we may elect of any component covered under this service warranty.

Any parts or components considered covered by this warranty shall be returned freight prepare to Applied Electronics. Return freight shall be paid by Applied Electronics.

This warrnaty may be voided if the product has been adversely effected or tampered with in any way.

This service warranty is separate from the original manufacturers warranty. In no event shall Applied Electronics be liable for any loss or damages arising out of any such defective component or workmanship.

Pursuant to section 28.1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

7

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R9-14-404(A)

ARIZONA DEPARTMENT OF HEALTH SERVICES

STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 5000*

AGENCY	rucson police QA SPECIALIST 1erry S. Gallegos 2884
INTOXILYZE	Print Name) Ori 17 29 2006 TIME 0945
	Display reads "READY TO START" or "PUSH BUTTON TO START TEST."
DIAGNOSTIC	DVM Test check. Setting should be between .200 and .600. Mode selection switch S2 on, S1 and S3 off or keyboard menu selection "H". Reading is .340. Display Test check. Mode selection switch S1 on and S2 and S3 off or keyboard menu selection "V". Printer Test check. Mode selection switch S1, S2, S3 off or keyboard menu selection "P". Clock time check. Mode selection switch S10 on or keyboard menu selection "E". Date check. Mode selection switch S11 on or keyboard menu selection "E".
N/A Instrumen	AL TESTS Alcohol free subject Test result 0.000 AC Error recognition logic system functioning Invalid test printed Proper sample recognition system Invalid sample printed Deficient sample printed Completeness of sample purge with collection tube** Calibration standard 0.080 AC Results: 0.077 AC and 0.080 AC t operating properly and accurately. YES NO
SIGNATURE O. N/A at analysis.	lcohol concentration standard collected for subsequent

*WITH OR WITHOUT VAPOR RECIRCULATION AND WITH OR WITHOUT KEYBOARD **THIS STEP IS ONLY REQUIRED IF THIS DEVICE IS BEING USED FOR SAMPLE CAPTURE.

DHS/DSLS/Form C117 (Rev. 7-93)

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

2054 154

#15 #140 #15 #15 #15 #15 #15 #15 #15 #15 #15 #15	THATE FIRST OBSERVED THATE FIRST OBSERVED CALLEADON AND AND AND AND AND AND AND AND AND AN	INTOXILYZER? INSTRUMENT PRINTER CARD © 1986 by CMI INC.
	TIME PIRST CHRSTRUM INSTRUMENT LOCATION THE P	J.COH HI MAGINGS

3 of 6 154 Tucson Police Department Crime Laboratory

in The

T.


ன ் பைத்த

1.

12. 13. 13.1 14.1

· 医克里特 医克里特氏 医甲基基

45,1186.40 53

- 1995年8月 - 1995年8日 - 1995年 - 1995年 - 1995年 - 1995年8日


	and the state of t	
	표속가, 영광	- 17 - 3 + 3 - 2 M
	INVELID TEST	
	SAMPLE INTRODUCED BT IMPROFER TIME.	
		1 🛦
		#8
	SUBJECT S NAME	
		مام ا
ALL	ME FIRST OBSERVED	INSTRUMENT LOCATION
	Gallegos	20000
	4 all egos	28847
	ADDITIONAL INFORMATION AND/OR	REMARKS

EXHIBIT P

50f6 154

THIS REPORT PREPARED PURSUANT TO DUTY IMPOSED BY A.A.C. R9-14-404(A)

ARIZONA DEPARTMENT OF HEALTH SERVICES

STANDARD QUALITY ASSURANCE PROCEDURES INTOXILYZER MODEL 5000*

STANDARD CALIBRATION CHECK PROCEDURE

Agency	Tuc	son Police Department Date 4.17.2006 Time 0945
Intoxil	WZEY	Serial # 64-00/226 (#8) Location Lab
		S / //a as 300////-
QA Spec	ialı	st <u>Jerry J. Cheffens 2007</u>
		(Print Name)
()	1.	Pour a standard alcohol solution of known value into a
		clean dry simulator jar and assemble the simulator. Insure that a tight seal has been made.
		Standard value: 0.080 AC
(v ·)	2.	Turn on the simulator and allow the temperature to
()		reach 34°C+.2°C.
	3	Set Intoxilyzer mode selection in the ACA mode by
()	٥.	switching mode selection switch #9 on or selecting "C"
		on keyboard menu.
(V)	4.	Attach simulator to the simulator entrance port on the
` /'		Intoxilyzer.
(VV)	5.	Intoxilyzer 5000 display reads "READY TO START" or
/		"PUSH BUTTON".
$(VV)_{\perp}$	6.	Push Start Test button or press enter on keyboard.
		Insert card in response to display.
		Air blank completed.
(V V)	9.	Calibration check completed. Test results 0.077 AC and 0.080 AC
V/	1 0	Test results 0.077AC and 0.080 AC Air blank completed.
	11	When display reads Test Complete remove evidence card.
()	11.	Attach the card to the completed checklist.
	12.	Return mode selection switch #9 to off position after
(- /		all calibration checks are complete or type Q and enter
		on keyboar ϕ , ϕ
SIGNAT	URE	Sling S. Gally
*WITH	or W	ITHOUT VAPOR RECIRCULATION AND WITH OR WITHOUT KEYBOARD

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.

DHS/DSLS/Form C116 (Rev. 7-93)

	- ·		60f6 154 pt
FEGURAL SIGNAL COROL SIGNAL COROL INC. 184-0812.7256 80 64-881226 04717786 80 VALUE TIME	AIR BLANK .0000 09:56 *SUBUECT TEST .042 09:58 AIR BLANK .000 09:58 * DEFICIENT SAMPLE - VALUE PRINTED WAS HIGHEST OBTHINES.	TIME FIRST OBSERVED TIME FIRST OBSERVED CLOCKED NASHIUMENT LOCATION ANNITONAL INFORMATION AND OR HE MARKS	INTOXILYZER' INSTRUMEN I PRINIFR CARD
FEUSRAH, GIGAR, LUME, 7 CH. 1835 INIURILYZRA - HIDORGE, ANALYZER AZ UDGE, BBBG SA 84-681228 BRZIZZBE TEST BHC WELLE		148 LUB LUB LUB LUB LUB LUB LUB LU	Sweethrath INTOXILYZER' INSTRUMENT PRINTER CARD C' 1986 by CMI INC



TUCSON POLICE DEPARTMENT CRIME LABORATORY

INTOXILYZER SERVICE RECORD



QAS: Terry S.	Gallegos 28847	
Intoxilyzer Serial Number:	64-001226 (#8)	
Date Returned to Service:	4.17.06	